

FIG. 9

Side Reinforces




FIG. 10






FIG. 11








Back Load Cell Mounting




Pillar Mounting Support







Back Load Cell Mounting

















**FIG. 25**







**FIG. 26**










**FIG. 27**






**FIG. 28**









Ramp and Hinge Assembly





Wheel Assembly





**FIG. 43**




**FIG. 44**














**FIG. 49**




**FIG. 50**




**FIG. 51**







**FIG. 55**



**FIG. 56**




**FIG. 57**






**FIG. 58**

Ultrasonic/Heat  
Welding Inserts



**FIG. 59**




This page is not part of  
the document!

**US2004032609 / 2005-033637**


**2/2**

Date: 2 juin 2005


Recipient: IB




**FIG. 64**



**FIG. 65**



**FIG. 66**



**FIG. 67**

Key Pad Connector Outlet




FIG. 68A




FIG. 68B





FIG. 69







**FIG. 70**




**FIG. 71**




**FIG. 72**




**FIG. 73**




**FIG. 73A**



**FIG. 73B**



**FIG. 73C**



Locking Disk

**FIG. 73D**

Screw




FIG. 76




FIG. 75






FIG. 74

10A






FIG. 80







FIG. 79






**FIG. 83**




**FIG. 84**




**FIG. 85**

Weight 28 Kg (61.5 lb)




**FIG. 86**




**FIG. 87**







**FIG. 89**




**FIG. 90**



**FIG. 91**




**FIG. 92A**




Weight 48 Kg (105.5 lb)


**FIG. 92B**




**FIG. 92**




**FIG. 93**




**FIG. 94**




**FIG. 95**




**FIG. 96**




**FIG. 97**





**FIG. 98**




**FIG. 99**




**FIG. 100**







**FIG. 103**




**FIG. 104**




**FIG. 105**



**FIG. 106**







**FIG. 107**




**FIG. 108**










**FIG. 112**




**FIG. 113**







**FIG. 116**




**FIG. 117**




**FIG. 118**




**FIG. 119**







**FIG. 120**




**FIG. 121**




**FIG. 122**







**FIG. 127**




**FIG. 128**




**FIG. 129**




**FIG. 131**




**FIG. 130**



**FIG. 132**




**FIG. 133**




**FIG. 134**







**FIG. 135**






**FIG. 136**




**FIG. 137**




**FIG. 138**







**FIG. 141**




**FIG. 142**




**FIG. 143**



**FIG. 144**




**FIG. 145**




**FIG. 146**


**FIG. 147**




**FIG. 148**




**FIG. 149**




**FIG. 150**




**FIG. 152**




**FIG. 153**



**FIG. 154**



**FIG. 156**



**FIG. 157**











FIG. 158







**FIG. 159**

**FIG. 160**


**FIG. 161****FIG. 162****FIG. 163****FIG. 164****FIG. 165**




**FIG. 166**




**FIG. 167A**




**FIG. 167B**




**FIG. 168**




**FIG. 169**




**FIG. 170**




**FIG. 171**




**FIG. 172**







**FIG. 173**














**FIG. 174**









**FIG. 175**







**FIG. 176****FIG. 177****FIG. 178****FIG. 179**

**FIG. 180****FIG. 181****FIG. 182****FIG. 183****FIG. 184**

**FIG. 185****FIG. 186****FIG. 187****FIG. 188****FIG. 189****FIG. 190**



**FIG. 191****FIG. 192****FIG. 193****FIG. 194****FIG. 195****FIG. 196**

**FIG. 197****FIG. 198****FIG. 199****FIG. 200****FIG. 202****FIG. 203**




FIG. 201

**This Page is Inserted by IFW Indexing and Scanning  
Operations and is not part of the Official Record**

**BEST AVAILABLE IMAGES**

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images include but are not limited to the items checked:

- ☐ **BLACK BORDERS**
- ☐ **IMAGE CUT OFF AT TOP, BOTTOM OR SIDES**
- ☐ **FADED TEXT OR DRAWING**
- ☐ **BLURRED OR ILLEGIBLE TEXT OR DRAWING**
- ☐ **SKEWED/SLANTED IMAGES**
- ☐ **COLOR OR BLACK AND WHITE PHOTOGRAPHS**
- ☐ **GRAY SCALE DOCUMENTS**
- ☐ **LINES OR MARKS ON ORIGINAL DOCUMENT**
- ☐ **REFERENCE(S) OR EXHIBIT(S) SUBMITTED ARE POOR QUALITY**
- ☒ **OTHER:** \_\_\_\_\_

**IMAGES ARE BEST AVAILABLE COPY.**

**As rescanning these documents will not correct the image problems checked, please do not report these problems to the IFW Image Problem Mailbox.**